



# ENTRUST

---

## Firmware Release Notes

### Entrust Desktop Printer Firmware

This document provides a summary of the new features and updates to the Sigma DS and EM Series Direct to Card Printers firmware.

---

#### Version Information

<b>Firmware Version</b>	D4.3.1-SP1
Release Date	January 2024
Update of Released Version	D4.3.1
<b>Component Versions:</b>	
• Printer	D4.3.1-5004
• Printer BSP	D4.1.22-14
• Embosser Firmware Version	E1.1.54-3
• Laminator Firmware Version	L1.1.6-16
• TIM Impresser Firmware Version	I1.1.3-2
• RIM Indenter Firmware Version	N1.1.2-2
• LCM UV Cure Firmware Version	V1.1.0-9
• Multi-hopper Firmware Version	M1.3.2-2
• OpenCard Plug-in Version	PLG.1.31-4
• Smart Card Coupler	DE-ABCM5_CCID_DC_230712

## D4.3.1-SP1 Firmware Release

### New Feature

- 3 input / 3 output multi-hopper support.



Due to a limitation in the D4.3.1-SP1 Sigma printer firmware, client applications will not detect the 3 input / 3 output multi-hopper exception slot. This may result in an inability to pick cards from the exception slot of the 3 input / 3 output multi-hopper. This limitation will be resolved in a future firmware release.

### Improvements

- Fixed rare issue of firmware updates corrupting printer firmware.

### Security

- PHP updated to fix CVE-2023-3823 and CVE-2023-3824.
- LLMNR protocol disabled on ethernet.